



## Overview

---

These release notes address the notable changes and information about the ControlSpace Designer software release ControlSpace Designer 5.10.2. ControlSpace Designer 5.10.2 updates ControlSpace Designer 5.10.1 with two additional changes.

For additional information regarding the ControlSpace Designer software see:

[pro.bose.com/en\\_us/products/software/signal\\_processing/controlspace\\_designer.html](https://pro.bose.com/en_us/products/software/signal_processing/controlspace_designer.html)

## ControlSpace Designer software 5.10.2 (released June 2022)

---

The following issues were addressed in this release:

### General Issues

1. Fixed defect in ControlSpace Designer 5.10.1 where the app could crash after selecting **Rename Selection** after selecting a group of signal processing blocks.
2. Updated help file guidance on performing Dante updates through Dante Controller with Dante Updater. We now recommend making sure the **Allow rollback to previous versions** checkbox is selected and the **Allow override of device matching** checkbox is still **not** selected.
3. Adjusted default **conference room.csp** sample file settings so that analog pre-gain is now set to 0dB with phantom-power off so 'pop' noises aren't heard through connected loudspeakers when you adjust those settings.

## ControlSpace Designer software 5.10.1 (released April 2022)

---

The following issues were addressed in this release:

### General Issues

1. Fixed issue from 5.10 that affected customers in Europe. Customers using Windows configured for regions that utilize commas as decimal separators were unable to connect to devices using ControlSpace Designer 5.10. ControlSpace Designer 5.10.1 was released to address this issue.

## ControlSpace Designer software 5.10 (released March 2022)

---

### Changes

This release includes the following changes:

1. The Realtime EQ functionality has been changed to allow the user to select which version will be employed, Legacy or Realtime. Old projects opened with ControlSpace Designer 5.10 will automatically utilize the Legacy implementation until the user specifies that Realtime EQ will be employed. New projects will utilize Realtime EQ as default.
2. When Dante firmware within the system is not compatible with the ControlSpace Designer version you will not be able to go online with the system.

3. A new version of firmware for the MSA12X is included which addresses the no bootup in cold environments issue.
4. The TFTP Server utilized in an AEC update is only active when an AEC update is taking place.
5. Update FS360P II HPF EQ - updates HPF to 60 Hz and corrects limiter settings for optional lo-z (low impedance) usage.
6. The release of ControlSpace Designer software utilizes a new application installer. Installation is performed as expected with a simplified and faster workflow.

## **New Features / Improvements**

This release includes the following new and improved functionality:

1. The Serial Out block within ESP and EX now supports sending serial commands via TCP and UDP as well as the existing RS232 interface present on the hardware.
2. Legacy Dante endpoints, (EP22-D, EP40-D, WP22B-D and WP22BU-D), are now listed in the Dante Endpoints section of the SP Tool Kit for ControlSpace EX Processors. When an Endpoint's IO is added to an ESP/EX processor the Dante routing is automatically configured.
3. The Device Status window now displays the connection status of the Dante Endpoints included in the system design.
4. PowerSpace and PowerSpace+ devices are now available within the Device List for use in the Project View. These are display only, and there is no ControlSpace system control of a PowerSpace+ Device.
5. A new expanded logging mode has been added to ControlSpace Designer software to assist PTS, Quality and Software teams, and RSEs when troubleshooting escalated customer support sessions.

## **Fixes**

The following issues were addressed in this release:

### **Security**

1. The ESP and EX firmware included with ControlSpace Designer 5.10 includes important security updates. It is highly recommended to update to the firmware included in this release.

### **General Issues**

1. Fixed issue in AEC update dialog where incorrect device name is displayed in status message.
2. Corrected product name for IZA devices within Devices List.
3. Addressed issue where AmpLink block is not present on a duplicated ESP or EX processor.
4. When a processor is added to a Project File which only contains PowerMatch amplifiers it is now set as the default Real Time Clock (RTC).
5. Fixed issue with search function in ControlSpace Designer embedded help file.
6. Fixed issue opening project files containing AmpLink blocks.
7. Fixed issue where ESP and EX processors may produce click noise during bootup.

## **Audio Processing**

1. Within a parametric EQ, the Bypass All will properly bypass all EQ bands, regardless of their individual bypass state.
2. Fixed issue which caused AmpLink block to not be present within SP Toolkit after it is deleted from an ESP processor so that it can be re-added to the processor/design.
3. Fixed issue related to user defined gain being properly retained within MSA12X after power cycle.
4. Addressed issue where MSA12X gain is reset to 0dB on restart.
5. Addressed issue where the FS360P II SEQ was using the incorrect values for the high pass and protection limiters.
6. Fixed issue saving group gain offsets in Parameter Sets.
7. Fixed issue where parameter Sets invoked by ControlSpace Designer are not always applied to ESP-00 II.

## **Control**

1. Fixed issue which causes processor to become unresponsive when a large quantity of SolP message requests are received continuously.
2. Addressed issue related where a Parameter Set is not recalled correctly when recalled via Parameter Set Recall Block.
3. Addressed issue where the logic out indicator of a meter block is not working properly.
4. Addressed issue where the logic out indicator of a ducker block is not working properly =
5. Fixed issue where CC-1D/2D/3D controllers do not load mute-on state of PowerMatch and PowerShare-D outputs.
6. Fixed issue where CC-2D/3D controllers do not correctly display selected source when recalled by a Parameter Set.

## **Dante**

1. Addressed issue where Dante devices are shown as connected when they are not present on the network.

## ControlSpace Remote

---

This release is compatible with ControlSpace Remote version 2.10.

## 3rd Party Control

---

This release is compatible with Sennheiser TCC2 firmware version 1.8.0.

## Firmware Versions

---

This release of ControlSpace Designer software requires a firmware for specific devices to enable the functionality included in this release. Updated firmware versions are noted with shading in the following table:

Devices	Device FW	Dante FW
ESP-00 II	5.110	3.0.1
ESP-880/880A/880AD/1240/1240A/1240AD/1600/4120	3.620	3.0.1
EX-12AEC/440C/1280/1280C	2.520	3.0.2
PM4250N/4500N/8250N/8500N	3.820	3.0.1
PS404D/604D	1.600	3.0.0
EX-4ML/8ML	2.000	3.0.0
EX-UH	2.000	3.0.0
WP22B/BU-D	-	5.0.0
EP22B/40-D	-	5.0.0
CC-64	1.120	-
CC-1D/2D/3D	0.914	-
MSA12X	1.052	3.0.0

## Known Issues, Defects and Limitations

---

The following are the known issues and defects with this release. Information included here can be useful when troubleshooting issues with software or hardware operation:

### Signal Processing

1. If a USB Input Module is not wired to an Output Module, that Module will not show Metering data.

### ControlSpace Designer Logic Blocks

1. Assigning a Logic Action from an ESP-00 to a Trigger on an EX-1280 will result in an error.
2. The states of Logic Connectors within the Logic Wiring View may sometimes show the incorrect state. This does not affect the functionality.
3. If you are experiencing issues with go-online time or ControlSpace Designer crashes when going online, consider dragging over Logic blocks instead of copy/pasting Logic blocks.
4. If you are finding ControlSpace Designer crashes when going online with a large number of Logic routes try going online from project view.

### Dante End Points

1. The EX-8ML may boot up with a Link Local address upon first use, rather than DHCP. Rebooting the device will then revert the address to DHCP.

### Telephone Call Functionality

1. PSTN and VoIP Ring and Voice Levels are not being properly set. There is no difference in audible level between 0 dB and +10 dB.

### ControlSpace Remote

1. On an Avaya system It is not possible to end a VoIP call with ControlSpace Remote when the Far End is in a "Hold" state.

### Other Issues

1. When programming Selectors, Gains, Analog Inputs/Outputs for GPI digital, they may not function when using EX-1280C with Legacy devices.
2. PowerMatch will not alert the user to a Digital Audio loss (Dante, AmpLink, ESPLink, CobraNet or other Digital Audio Sources).

## Minimum System Requirements

---

The following are the minimum system requirements for running ControlSpace Designer software:

Microsoft Windows 10 Version 2004 (or later)

1 GHz processor (or better)

512 MB of available RAM (1 GB recommended)

512 MB of available disk space

Minimum resolution of 1366x768 WXGA

1 available USB port

1 available Ethernet port, 100 Mbps minimum, (1 Gbps recommended)

ControlSpace Designer also requires the Microsoft® Visual C++ 2019 runtime library. If not already installed, this will be installed automatically as part of the ControlSpace Designer installation.

### Notes:

1. Microsoft Windows XP, 8, and 8.1 are no longer officially supported.
2. Microsoft Windows 11 is not officially supported.