



### Overview

These release notes address the notable changes and information about the ControlSpace Designer software release version 5.10.3. Version 5.10.3 improves Version 5.10.2 with one additional change.

For additional information regarding the ControlSpace Designer software see: pro.bose.com/en\_us/products/software/signal\_processing/controlspace\_designer.html

**Updates in ControlSpace Designer software 5.10.3** (Released August 2022)

### **Fixes**

1. Fixed defect that could occur when using ControlSpace Designer 5.9 or later where PowerMatch amplifiers with Dante cards may not boot correctly.

**Updates in ControlSpace Designer software 5.10.2** (Released June 2022)

### **Fixes**

- 1. Fixed defect in 5.10.1 where ControlSpace Designer could crash when using the **Rename**Selection from the right-click menu after highlighting a group of signal processing blocks.
- Updated help file guidance on performing Dante updates through Dante Updater in Dante
  Controller. Our help file now recommends making sure the Allow rollback to previous versions
  checkbox is selected and the Allow override of device matching checkbox is still not selected.
- 3. Adjusted default **conference room.csp** sample file settings so that analog pre-gain is now set to 0 dB with phantom power off so "pop" noises aren't heard through connected loudspeakers when you adjust those settings.

**Updates in ControlSpace Designer software 5.10.1** (Released April 2022)

#### **Fixes**

1. Fixed issue from 5.10 that affected customers in Europe. Customers using Windows configured for regions that use commas as decimal separators were unable to connect to devices using ControlSpace Designer 5.10.

**Updates in ControlSpace Designer software 5.10** (Released March 2022)

# Changes

1. The Realtime EQ functionality has been changed to allow the user to select which version will be employed, Legacy or Realtime. Old projects opened with ControlSpace Designer 5.10 will automatically use the Legacy implementation until the user specifies that Realtime EQ will be employed. New projects will use Realtime EQ as default.

Date: August 2022 BOSE Professional Revision: 1.0

- 2. When Dante firmware within the system is not compatible with the ControlSpace Designer version you will not be able to go online with the system.
- 3. A new version of firmware for the MSA12X is included which addresses an issue in which the loudspeaker may not boot up in cold environments.
- 4. The TFTP Server used in an AEC update is only active when an AEC update is taking place.
- 5. Updates FS360P II HPF EQ to 60 Hz and corrects limiter settings for optional lo-Z (low-impedance) usage.
- 6. This release uses a new application installer. Installation is performed as expected with a simplified and faster workflow.

## **New Features / Improvements**

- 1. The Serial Out block within ESP and EX now supports sending serial commands via TCP and UDP as well as the existing RS-232 interface on the hardware.
- 2. Legacy Dante endpoints (EP22-D, EP40-D, WP22B-D, and WP22BU-D) are now listed in the Dante Endpoints section of the SP Tool Kit for ControlSpace EX Processors. When an endpoint's IO is added to an ESP/EX processor, the Dante routing is automatically configured.
- 3. The Device Status window now displays the connection status of the Dante Endpoints included in the system design.
- 4. PowerSpace and PowerSpace+ devices are now available within the Device List for use in the Project View. These are display only, and there is no ControlSpace system control of a PowerSpace+ Device.
- 5. A new expanded logging mode has been added to assist PTS, Quality and Software teams, and RSEs when troubleshooting escalated customer support sessions.

#### **Fixes**

### Security

1. The ESP and EX firmware included with ControlSpace Designer 5.10 includes important security updates. We highly recommend updating with the firmware included in this release.

### **General Issues**

- 1. Fixed issue in AEC update message where incorrect device name is displayed in status message.
- 2. Corrected product name for IZA devices in Device List.
- 3. Addressed issue where AmpLink block is not present on a duplicated ESP or EX processor.
- 4. When a processor is added to a project file that contains only PowerMatch amplifiers, that processor is now set as the default Real Time Clock (RTC).
- 5. Fixed issue with search function in embedded help file.

- 6. Fixed issue opening project files containing AmpLink blocks.
- 7. Fixed issue where ESP and EX processors may produce click noise during bootup.

### **Audio Processing**

- 1. Within a Parametric EQ, the Bypass All option will properly bypass all EQ bands, regardless of their individual bypass state.
- 2. Fixed issue which caused AmpLink block to not be present within SP Tool Kit after it is deleted from an ESP processor so that it can be readded to the processor/design.
- 3. Fixed issue related to user-defined gain being properly retained within MSA12X after power cycle.
- 4. Addressed issue where MSA12X gain is reset to 0 dB on restart.
- 5. Addressed issue where the FS360P II SEQ was using the incorrect values for the high-pass and protection limiters.
- 6. Fixed issue saving group gain offsets in Parameter Sets.
- 7. Fixed issue where Parameter Sets invoked by ControlSpace Designer are not always applied to ESP-00 II.

### Control

- 1. Fixed issue which causes processor to become unresponsive when a large quantity of SoIP message requests is received continuously.
- 2. Addressed issue related where a Parameter Set is not recalled correctly when recalled via Parameter Set Recall block.
- 3. Addressed issue where the Logic Output indicator of a Meter block does not work properly.
- 4. Addressed issue where the Logic Output indicator of a Ducker block does not work properly.
- 5. Fixed issue where CC-1D/CC-2D/CC-3D controllers do not load mute-on state of PowerMatch and PowerShare-D outputs.
- 6. Fixed issue where CC-2D/CC-3D controllers do not correctly display selected source when recalled by a Parameter Set.

### **Dante**

1. Addressed issue where Dante devices are shown as connected when they are not present on the network.

# **ControlSpace Remote**

This release is compatible with ControlSpace Remote version 2.10.

# **Third-party Control**

This release is compatible with Sennheiser TCC2 firmware version 1.8.0.

## **Firmware Versions**

This release of ControlSpace Designer software requires a firmware for specific devices to enable the functionality included in this release. Updated firmware versions are noted with shading in the following table:

Device(s)	Device FW	Dante FW
ESP-00 II	5.110	3.0.1
ESP-880/880A/880AD/1240/1240A/1240AD/1600/4120	3.620	3.0.1
EX-12AEC/440C/1280/1280C	2.520	3.0.2
PM4250N/4500N/8250N/8500N	3.820	3.0.1
PS404D/604D	1.600	3.0.0
EX-4ML/8ML	2.000	3.0.0
EX-UH	2.000	3.0.0
WP22B/BU-D	-	5.0.0
EP22B/40-D	-	5.0.0
CC-64	1.120	-
CC-1D/2D/3D	0.914	-
MSA12X	1.052	3.0.0

### **Known Issues, Defects and Limitations**

The following are the known issues and defects with this release. Information included here can be useful when troubleshooting issues with software or hardware operation:

### **Signal Processing**

1. If a USB Input module is not wired to an Output module, that module will not show metering data.

# **ControlSpace Designer Logic Blocks**

- 1. Assigning a logic action from an ESP-00 to a trigger on an EX-1280 will result in an error.
- 2. The states of logic connectors within the Logic Wiring View may sometimes show the incorrect state. This does not affect the functionality.
- 3. If you are experiencing issues with go-online time or ControlSpace Designer crashes when going online, consider dragging and dropping logic blocks instead of copying and pasting them.
- 4. If you are finding ControlSpace Designer crashes when going online with a large number of logic routes, try going online from Project View.

#### **Dante End Points**

1. The EX-8ML may boot up with a link local address upon first use rather than DHCP. Rebooting the device will then revert the address to DHCP.

### **Telephone Call Functionality**

1. PSTN and VoIP ring and voice levels are not being properly set. There is no difference in audible level between 0 dB and +10 dB.

### **ControlSpace Remote**

1. On an Avaya system, it is not possible to end a VoIP call with ControlSpace Remote when the far end is in a hold state.

## Other Issues

- 1. When programming selectors, gains, analog inputs/outputs for digital GPI, they may not function when using EX-1280C with legacy devices.
- 2. PowerMatch will not alert the user to a digital audio loss (Dante, AmpLink, ESPLink, CobraNet or other digital audio sources).

## **Minimum System Requirements**

The following are the minimum system requirements for using ControlSpace Designer software:

- Microsoft Windows 10 version 2004 or later
- 1 GHz processor (or better)
- 512 MB of available RAM (1 GB recommended)
- 512 MB of available disk space
- Minimum resolution of 1366x768 WXGA
- 1 available USB port
- 1 available Ethernet port, 100 Mbps minimum, (1 Gbps recommended)
- ControlSpace Designer also requires the Microsoft® Visual C++ 2019 runtime library. If required, this will be installed automatically as part of the ControlSpace Designer installation.

#### **Notes:**

- 1. Microsoft Windows XP, 8, and 8.1 are no longer officially supported.
- 2. Microsoft Windows 11 is not officially supported.