



CSP Firmware v1.0.7

Release Notes

May 17, 2022

Supported Web Browsers

Browser	Minimum Version Required
Google Chrome	89.0.4389.114
Mozilla Firefox	87.0
Microsoft Edge	89.0.774.75

New Features, Fixes & Improvements

Firmware v1.0.7 for CSP-428/CSP-1248 includes support for the following:

- Resolved a rare issue where an audible artifact on analog outputs could occur during startup.

Known Issues, Defects & Limitations

The following are the known issues and defects with this release. Information included here can be useful when troubleshooting issues with software or hardware operation.

General Issues (same as the v1.0.5 release notes)

1. If you have calibrated AutoVolume for a listening area and then calibrate it a second time, the previous calibration is not removed until the calibration process reaches Step 3 (during which the system plays the active input for one minute).
2. The Speaker EQ graph (under **Configuration > Outputs**) will not display the following **Type** selections for **High Pass/Low Pass** for predefined speakers but these filters are being applied to the audio:
 - Butterworth 36 (± 36 dB/octave)
 - Butterworth 48 (± 48 dB/octave)

3. Backtracking in Quick Setup Wizard Output configuration can cause channels not to show up as assignable. A workaround is to exit and restart the Quick Setup Wizard.
4. The initial Dynamic EQ calibration level can be much louder than expected (0 dB). We recommend manually entering **-32 dB** into the initial calibration screen prior to making adjustments. Alternatively, you can refresh the browser just before calibrating Dynamic EQ.
5. AutoVolume metering does not display if AutoVolume is turned on by ControlSpace Remote (CSR) or by a Scheduled Event. To reenble the metering, refresh the browser after AutoVolume is turned on.
6. The Dashboard View does not automatically refresh to show the changes made (e.g., source change). To show these changes, refresh the browser.

Discovery Tool Issues

1. If the computer configuring the CSP is using a dual-NIC (network interface card) setup, and if the computer is connected to a Wi-Fi network and using a link-local direct connection, the Discovery Tool will be unable to identify the IP address of the CSP.

Browser-specific Issues

1. **Microsoft Edge:** While using the Quick Setup Wizard to configure inputs, some options (e.g., the **Stereo** checkbox, the **Phantom** switch) may not appear as available. To fix this, click **Continue** to skip to the next page in the Quick Setup Wizard and then click **Back** to return to the previous page.
2. **Internet Explorer:** If another web browser has already connected to a CSP and if you use Internet Explorer to connect to the same CSP, you will see an incorrect **Starting CSP Configuration Utility** message instead of the correct error message: **Multiple Browsers Connected**.